



## **Carburetor Information**

**U.S. CB750 Models 1969-1978**


[...Home...](#) [...Garage...](#) [...Carb Info Index...](#)

### **71-76 CB750 Idle Screw Modification for Free Flowing Air Cleaners**

Nearly all aftermarket carb kits come with newer idle screws that have a pre-bored metering hole in the end. I'm not sure if this is an EPA thing or not, but running free flowing air cleaners of any kind on the 71-76 style CB750 carbs often presents a bit of a problem with these pre metered idle screws. The stock air cleaners introduce some vacuum to the intake side of the carbs that aftermarket air filters (or Vstacks) eliminates. The problem is the idle screws cannot be adjusted in far enough to compensate for the additional air flow and reduced draw on the idle circuit. Add drag or open headers and the problem is often more noticeable. Below is a pic of an idle screw out of a new rebuild kit showing the pre metered bore in the center which allows air to pass into the circuit even with the screw turned in all the way in to where it seats.



Boring out the pilot jets is not a solution as this alters the transition point from idle to low RPMs and actually creates a "fat spot" or spot in the throttle throw that runs too rich. This fat spot often makes the bike cough or stutter under light load (like pulling away from a stop while a cop is watching). Since the idle screws on the 71-76 style carbs controls the amount of air into the low end circuit (not just idle) the solution is to eliminate the pre metered bore so the screw can be turned in far enough to balance the fuel to air mixture.



JB Weld is impervious to gas, withstands heat quite well, and holds up to vibration extremely well so it is ideal for plugging the holes in the idle screw. The idle screw must be squeaky clean! Dip it in MEK or another solvent that works to dissolve oils that may have been left behind during the manufacturing and packaging process. Mix a small amount of JB Weld and push the tip of the screw down into the JB Weld repeatedly until it begins to squeeze out of the holes on the sides (see image above). Be VERY CAREFUL not to get any on the threads! If you do you will have to immediately clean the idle screw thoroughly in denatured or rubbing alcohol before the JB Weld sets. Diligently wipe any excess JB Weld from the shaft and end of the idle screw with a clean paper towel until it is a bit concave in the holes as shown above. Be absolutely sure you have the shaft clean of any JB Weld, in particular the taper as this seats in the carb casting. To speed up the curing process you can bake the screws in your oven at 200 degrees for about 45 minutes and they will be ready to go. Then tune the idle as you would normally.

Tip: It would not hurt to carry a screwdriver with you and ride around roads where you would be stopping and cruising slowly, and as much as possible in 5th gear so you are spending as much riding time using the low end circuit. Pay attention to how the bike sounds as you slowly pull away from a stop. If it stutters a little or balks a bit back the screw out 1/8 turn and test again. If it pulls away fine but has a stubborn idle turn the screw in 1/8 turn and test again. You may have to just nudge the screw to find that sweet spot but in no time the bike will lope at idle yet pull away from a stop smoothly. A vacuum sync before hand is strongly recommended.

Houndog750

*Original Content Copyright 2009, all rights reserved  
Exclusive permissions granted solely to hondachopper.com*